WIPP EOC Activated - Update

August 4, 2015

WIPP Emergency Communications

Updated Information

- At approximately 6 p.m. MT, Radiological Control Technicians detected minute levels of radiation on the filter at Station B where air is exhausted from the WIPP underground.
- As a precaution, WIPP personnel were directed to shelter in place.
- Radiological control technicians have NOT received any indication of a release underground.
- There is no indication of any kind of radiological release leaving the WIPP site.
- All WIPP personnel have been accounted for.
- The WIPP Emergency Operations Center was declared operational at 7:45 p.m.